

Uniformance PHD – Honeywell Certified Associate (HCA) – Administration Certification Flow Chart

**Pre-requisite
Courses**

1. UNI-0004



UNI-0004-CT

Uniformance PHD:
Advanced -
Interfaces and
System
Administration -
Certified Associate

Administration Certification

Uniformance PHD – Honeywell Certified Associate (HCA) – Maintenance Certification Flow Chart

**Pre-requisite
Courses**

1. UNI-0003



Maintenance Certification

UNI-0003-CT
Uniformance PHD:
Fundamentals -
Process Studio,
Insight and System
Maintenance -
Certified Associate